
102D



INSTALLATION INSTRUCTIONS


Step 1: Drill holes for the desired location.

Determine your desired location for installation and make a mark for the location. Make mark where mounting screw will be placed as shown below. Drill hole at the mark.



Step 2: Pull Mounting

Place Pull to the desired location and screw from behind.



No portion of this document or any artwork contained herein should reproduced in any way without the written conset of ALLIED BRASS INC.