


- 11 Turn the drawer upside down. Line up the holes on the outside pieces with the holes on the runners (KDR & KDL), secure to the drawer using screws (L).

12 Turn the unit the right way up and insert the drawers.



13

The unit should now be assembled and ready to use.

