

9203D13 D13"H18"L3



install your chandelier. Please read all instructions carefully and thoroughly. If you have any questions please fell free chandelier for our customers. Our master craftsmen and We are dedicated to providing the finest quality crystal designer pride themselves on their attention to detail. prompt, efficient service is our priority. Enclosed, are detailed instructions on how to properly. to call our toll free CHANDELIER HOTLINE AT:

1-888-388-3390 (L) C(B) US





WARNING!!!

CONTENTS ARE FRAGILE HANDLE WITH CARE

and installation. exercise extreme caution during unpacking of this chandelier are very delicate. Please The metal frame and crystal components

WARNING!!

After passing the main electrical wire through the 10mm pipe and connecting the pipe to the main body top connector, place all remaining pieces as shown in numerical order and in the orientation depicted. Refer to the parts list to avoid confusion between parts. The part numbers coincide.

- Rated 110-1807/60Ez, bulb 40W maximum
 Care should be taken to avoid demage to the surface of lighting and wire, wearing gloves is recommended when installing.
- 3. Connect black or red wire of the lighting to live wire and white or blue wire to neutral wire
- and double colored (or bare copper) wire to ground wire.

 4. Never install lighting on demp ceiling, the room should be dry and well ventilated.
- 5. Keep lighting eway from soid, alkali and other corrosive chemical or gas, clean the lighting with clean soft cloth only.
- Installation must be carried out by qualified electricism only.Disconnect the power before installing cleaning and replacing lighting.
- 8. Never cover the lighting when power is connected.
- 9. Firmess must be secured when installing ceiling tube, chain, pipe and other connecting parts.
- 10. Care should be taken to avoid demage when installing glass parts.
 11. All electrical components must be installed by a licensed electrician and in accordance.

14mm*8pcs


with the National Electrical Code and the appropriate local electrical codes. Make sure that the electrical supply to the chandelier is turned off at the main fuse or circuit breaker before doing any installation


2


(5)

9203 D13"H18"L3

Crystal Dressing Instructions









9203 D13"H18"L3

Diagram **Crystal Dressing**

When dressing the chandelier with the crystals please remembe to wear either rubber or cotton gloves. So as to prevent any





Connect both ends of J with G

8

Connect both ends of I with F

CANOPY PARTS LIST

ZA: Existing Electrical Box (not supplied)



ZB:Crossbar



ZC:Crossbar Screws x 2(not supplied)



ZD:Canopy lock



ZE:Canopy



ZF:Metal Ring



ZH:Ground Wire

ZG:Chain



ZI:Canopy Loop



ZJ:Electric Main




ZK: Junction Caps



(2)

CANOPY INSTALLATION DIAGRAM



9203 D13"H18"L3

Frame Assembly Instruxtions

Please read all instructions carefully. Before you proceed to install, make sure that the power supply is tamed off and off until installation is complete. Please note that each part has been assigned a letter. Please proceed in alphabetical order.

- 1. Install (Cast Canopy)01 to the electRic Box and wire properly.
- .using (Grourd Screw)04, Connect the Loose (chain Connector)02 on the (All thread)10.
- . Apply (Scroll Arm)03 to (Round Metal Cover)05 using (Ground Screw)04.
- 4. Loose the screw from (All thread)26, apply (Cast Bottom Finial)27 on the (All thread)26.
- 5. Dressing Crystal using Diagram provided

The end!

Fram Parts List

анинини

24-Nut

19-All thread



25-Bottom Cover

20-Cast Arm

21-All thread

26-All thread

22-Spring Seat

27-Cast Bottom Finial

23-Set Screw

9203 D13"H18"L3

CANOPY INSTALLATION INSTRUCTIONS

off until installation is complete. Please note that each part has install, make sure that the power supply is tamed off and been assigned a letter.Please proceed in alphabetical order. Please read all instructions carefully. Before you proceed to

ZA. Junction Box (not supplied)

ZB. Crossbar

ZC. Crossbar Screws

ZE. Canopy ZD. Canopy Loop

ZF. Metal Ring

ZG. Chain

ZH. Ground Wire

ZI. Canopy loop

ZK. Junction Caps ZJ. Electric loop

1. Attach the Crossbar (ZB) to the Junction Box (ZA) using the two crossbar screws (ZC) which are not supplied and should

already be in your box.

2. Slide the Metal Ring(ZF) back up over the canopy(ZE) pass the canopy loop(ZD)through canopy(ZE), connect with the threaded pipe underside of the crossbar.

3. Pass the electric loop(ZJ) and ground wire (ZH) through the chain(ZG), crossbar(ZB)until the end of the electric Loop(ZJ) reaches the the Metal Ring (ZF), the canopy (ZE), the canopy loop (ZD) and the junction box(A) where you can make the appropriate connections

4. Be sure when connecting the

5. Stow the excess wire in the junction box (ZA). wire use electrician approved junction caps(ZK)

6. Raise the canopy (ZE).

7. Metal Ring(ZF), attach canopy(ZE) to ceiling, slide Metal Ring(ZF) over canopy loop(ZD) and hold the canopy(ZE).

9203 D13"H18"L3 21 22 15 13 15 16 17 Frame Assembly Diagram 9 2 2 3 2 2 25 25 27 27 27 8 8 9203 D13"H18"L3 05-Round Metal Slice 02-chain Connector 01-Cast Canopy ® 04-Ground Screw 03-Scroll Arm Fram Parts List 06-Cast Column Cover 09-Top Cover 08-Mid Column 10-All thread 11-Set Screw 8 18-Cast Bobeche 17-Cast Socket 13-Sleeve cover 12-Cost Column 15-Set Screw 14-Socket 16-Washer 0