

Collection: Timber


Installation manual for:

LD5051D30C D30"H29"L8

## Installation instructions:

- 1.Black wire from ceiling(junction box) attaches to "L"wire from the fixture.
- 2. White wire from ceiling(junction box) attaches to "N"wire from the fixture.
- 3."E" wire from the fixture is attaced to the mounting bracket and an additional "E" wire from the mounting bracket must be secured to the junction box.
- 4. Secure mounting bracket to the junction box.
- 5.Insert screws(P2) in side of top unit the mounting bracket.
- 6. Fix the loop (P3) to screw tube, then cover the canopy (P4) and fix it by canopy ring(P5).
- 7.Install the bulbs(not included) into the lamp fixture.
- 8. Mounting the iron rod (11) (12) to the metal lamp body (10). (P11, P12, P11, P12.....).

The end!



## PARTS LIST

part	picture	Description	Qty	Check	list
P1		LA" Mounting bracket	1		
P2	_	5/32-32 Screw	2		
P3		Canopy loop (Canopy part)	1		
P4		Ø5.1″ canopy plat	1		
P5		Canopy ring (Canopy part)	1		
P6	<del></del>	L59"CHAINO4P Plain Design	1		
P7	\	ground wire	1		
P8	{	Power Cord 79" SPT-1-18# Brown	1		
P9		W1.5"*H1.7" Quick link	1		
P10	K	metal lamp body	1		
P11		D0. 2"*L13" iron rod	40		
P12		DO. 2"*L11" iron rod	40		
P13		E12 lampholder	8		
P14		D1.2"*L2" metal lampcap	8		