

INSTALLATION GUIDE



WaterBridge Wall-Mounted Exposed Showers

Mar 2014

Waterbridge Exposed Showers are plumbed to 1/2" copper lines. The Shower employs compression fittings to attach to plumbing lines that have been stubbed out. The hot and cold lines should be plumbed 8" on center. A copper template is included with the shower, to position the supply lines in the wall.

Some local plumbing codes require the use of a **remote anti-scald thermostatic mixing valve**. This valve may be installed in the wall directly behind the shower face plate, in a recess panel, under the floor, or anywhere between the uninterrupted hot water supply and fixture.



Spec Sheet & Installation Instructions Included in Box

Remote (anti-scald) Mixing Valve Installation:

Prior to installing this valve, make sure that all lines have been flushed of any debris. The hot and cold water must be fully operational at the valve inlets or the unit will not function properly even during testing or flushing.

Close both the hot and cold water supply shut-off valves and bleed the remaining water from the system.

Clean pipe ends and solder both the hot and the cold connections at the locations locate on the valve body. The valve cartridges do not have to be removed before soldering.

After soldering, check for leaks.

Note: When using with a recirculation system, re-circulated water must enter downstream to the thermostatic system.

<u>WARNING</u>: Temperatures exceeding 110 degrees are dangerous and may cause scalding, server injury or death. This valve is NOT factory preset. Installer must make the proper adjustments.

800.330.5553 | f 707.789.9201 | info@sonomaforge.com

INSTALLATION GUIDE WaterBridge Wall-Mounted Exposed Showers



Mar 2014





INSTALLATION GUIDE

WaterBridge Wall-Mounted Exposed Showers

Mar 2014

Shower Body Installation

- 1) Determine a comfortable height for the rain head and shower controls.
- 2) Install the **mounting plate** pictured below (included with shower) into the wall. Additional blocking should be installed into the wall behind the mounting plate for additional support.



- 3) Run 1/2" copper supply lines through the mounting plate and solder in place to make the lines rigid. Leave at least 2-1/2" stubbed out of the finished wall. Cap lines until ready to install trim.
- 4) Remove the back plate from the shower valve body by unscrewing the compression nuts. Take care not to damage or misplace the ferrules.

NOTE:

For Shower Models (870 & 880) with Tub Filler/Foot Wash; Install the tub spout and optional extension piece prior to installation the shower on the wall.

- 5) Uncap the supply lines, and cut them down to 1-1/16" to 1-9/16" from the finished wall.
- 6) Slide the shower back plate over the lines, and screw the back plate firmly to the wall. Care should be used to properly level the back plate, as this will align the entire shower.
- 7) Install the ferrules over the supply lines.



800.330.5553 | f 707.789.9201 | info@sonomaforge.com





INSTALLATION GUIDE

WaterBridge Wall-Mounted Exposed Showers

Mar 2014

- 12) Once the Shower Body is installed, the Shower Arm should be installed (again, employing Teflon tape, joint compound, and/or supplied square O-ring).
- 13) Then the Rain Head should be installed: (again, employing Teflon tape or joint compound)
 - a) Unscrew the collar from the top of the rain head.
 - b) Using an Allen wrench (not provided), thread the ball joint through the collar and into the shower arm until secure.
 - c) Supporting the head, tighten the collar back on to the top of the head.
 - d) Note: The shower head is shipped with a flow restrictor inside the ball joint. This can easily be removed for replacement.



- 14) Turn water supply on at source, and check for leaks.
- 15) Check volume controls and shut-off valves for proper function.

Care & Maintenance: No abrasives should be used to clean Sonoma Forge products. Mild soap and water can be used, and 100% carnauba wax can be applied to protect the finish.

All exterior plumbing should be winterized if freezing temperatures are expected.

800.330.5553 | f 707.789.9201 | info@sonomaforge.com