


INSTRUCTION

CE IP44




1


2

3


4



5




6



7

Prepare a 110V power source. Attach 2 screws onto the wall for mounting. Flip mirror over and open wiring box.




Put power cable through ring.

Push ring back down.

Screw down wire connections:
blue wire onto N
red wire onto L.

Make sure that the cable is threaded
through the piece above ring. Fasten
the screws to tighten cable.

8



9