


# INSTRUCTION

CE IP44




1


2

3


4



5




6



7

Prepare a 110V power source. Flip mirror over and open wiring box. Attach 2 screws onto the wall for mounting.




8

Put power cable through ring.

Push ring back down.

Screw down wire connections:  
blue wire onto N  
red wire onto L.

Make sure that the cable is threaded  
through the piece above ring. Fasten  
the screws to tighten cable.



9